Report #	Subject	Rec #	Description	Original Response	Status at 12/31/07	Follow-Up
	El Dorado County Court Security	2		Requires further	Has not been implemented but will be in future	In progress. Completion expected Feb. 2008

2006-07 First Midterm Report

Report #	Subject	Rec #	Description	Original Response	Status at 12/31/07	Follow-Up
GJ 06-019	Board of Supervisors Vacancy		Amend Section 203 of the County Charter to define when a	Requires further	Requires further analysis	BOS to discuss 01/08/08
	Board of Supervisors Vacancy	2R	ICOUNTY Charter to provide	Requires further analysis	Requires further analysis	BOS to discuss 01/08/08

2006-07 Final Report

1				•		
Report #	Subject	Rec #	Description	Original Response	Status at 12/31/07	Follow-Up
GJ 06-033	In-Home Support Services	2a	Provide respite care for providers.	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-039	Placerville Jail	4a	Review/Revise safety policy/procedures	Has not been	Has not been implemented but will be in future	Inmate transport and housing information
GJ 06-039	Placerville Jail	4b	Inrocedures	implemented but will	Has not been implemented but will be in future	Coordinate w/ OES

2006-07 Final Report (continued)

Report #	Subject	Rec #	Description	Original Response	Status at 12/31/07	Follow-Up
GJ 06-045	Government Center	1	Correct slippery condition of footbridge	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	Building B	3	Repair/Replace cooling tower	Has not been implemented but will be in future	Has not been implemented but will be in future	In progress. Completion expected: spring 2008
GJ 06-045	El Dorado Center	4	Repair/Replace worn carpet	Has not been implemented but will be in future	Has not been implemented but will be in future	In progress. Completion expected: Jan. 2008
GJ 06-045	El Dorado Center	5	Eliminate mold	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	El Dorado Center	8	Post emergency evacuation signs	Has not been implemented but will be in future	Has not been implemented but will be in future	In progress. Completion expected: Jan. 2008
GJ 06-045	SLT Library	13	Post emergency evacuation signs	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	SLT Library	14	Post correct maximum capacity sign	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	SLT Library	15	Install exit signs	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	SLT Administration Building	17	Repair leaks in roof	Has not been implemented but will be in future	Recommendation has been implemented.	None

			(continu	ed)		
GJ 06-045	SLT Administration Building	18	Eliminate the rodent problem	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	SLT Administration Building	19	Display prominent direction signs	Has not been implemented but will be in future	Has not been implemented but will be in future	spring, 2008
GJ 06-045	SLT Administration Building	20	Minimize or eliminate the source of the noise	Recommendation requires further analysis	Recommendation is not warranted	None
GJ 06-045	SLT Administration Building	21	Repair or replace carpet	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	SLT Administration Building	22	Repair or replace the exhaust fan	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	SLT Courthouse	23	Post emergency evacuation signs	Has not been implemented but will be in future	Has not been implemented but will be in future	In progress. Completion expected: Jan. 2008
GJ 06-045	SLT Courthouse	24	Install exit signage	Has not been implemented but will be in future	Has not been implemented but will be in future	In progress. Completion expected: Jan. 2008
GJ 06-045	SLT Courthouse	26	Install wheelchair access	Has not been implemented but will be in future	Recommendation has been implemented.	None
GJ 06-045	SLT Courthouse	27	Install parking lot lighting, security cameras	Requires further analysis	Recommendation has been implemented.	None
GJ 06-045	SLT Courthouse	28	Investigate and eliminate health hazard	Requires further analysis	Recommendation is not warranted	None
GJ 06-045	SLT Courthouse	30	Provide a secure holding cell	Requires further analysis	Recommendation is not warranted	None

2006-07 Final Report (continued)

			(continu	ea)		
						Budget
(. .1 06-049	Wraparound Program	1 1 5	lanalvsis	Has not been	Has not been	request for
				implemented but will	implemented but will be in	additional
				be in future	future	program
						slots
GJ 06-050	Information	1	IT Strategic Plan	Requires further	Requires further analysis	Yes
GJ 00-020	Technologies	es i	evaluation/ERP	analysis		res

2006-07 Final Report (continued)