18-1295 Printed Name: JEINNY Petri Signature: 530 957 9270 Phone: Address: jenipetria quail. com **E-Mail:**

CUP-A18-0005 AT&T has had 6 months to correct the site location which has been located by 2 of their surveyors 3' too close to the set back. The paper work submitted by them to planning is 3' off according to Peter Brewsters survey. How can you okay a site like that with paperwork in error and so many errors in the environmental assessment.

TITLe Report Needed Access is Civil To Be Fixed Later after Permit Potential Degregation of Luis Requisements FCC Mondated his -What in Goal as many Estate Jas Passible Redhights ADD more Na ADD C 9/4-9/4 or 9/10 NOCORS appertunet access Righ No over Burden acest myny my man, Search Ring By ATT. Real astate FCC aroup Elegales - Mar amount of House Holds Lack of Service at 10-1 What in the of FCC How now |4| 500 House holds 100 on more at End May Google Eve Eleveren - hænd kins mailer our rig Reporte

CUP-A18-0005 Site 2 Newtown Printed Name: JAMES DAVIS Signature: James That Phone: 916-934-9949 Address: 7134 TUNILI LANE PLACENULLE; LA 95630 E-Mail: N/A


AT&T presented a woefully inaccurate environmental assessment at this site. They show no mines or historical mining activity nearby. Sierra Rock is clearly visible to the south, the property adjacent to this property. Many acres of gravel and sand removed and 2 tunnels going north toward this site. The frog pong is 60' north of this site, and was Joesph Snows hydraulic water containment pond in 1854. The pond still stores water, also an air shaft to the north of the site 30' deep. Also 2 hydrolic cuts with possible tunnels N.W of the sire in line with gravel pit. AT&T has had time to do ground penetrating radar and has failed to properly asses this site. The tower needs to be relocated.

CUP-A18-0005 Site 2 Newtown
Printed Name: Trevor Joines
Signature: Total Sur
Phone: <u>530</u> 306-6935
Address:
E-Mail:

AT&T presented a woefully inaccurate environmental assessment at this site. They show no mines or historical mining activity nearby. Sierra Rock is clearly visible to the south, the property adjacent to this property. Many acres of gravel and sand removed and 2 tunnels going north toward this site. The frog pong is 60' north of this site, and was Joesph Snows hydraulic water containment pond in 1854. The pond still stores water, also an air shaft to the north of the site 30' deep. Also 2 hydrolic cuts with possible tunnels N.W of the sire in line with gravel pit. AT&T has had time to do ground penetrating radar and has failed to properly asses this site. The tower needs to be relocated.

Printed Name: Amber Spen C	2
Signature:	1
Phone:	
Address:	
E-Mail:	

CUP-A18-0005 AT&T has had 6 months to correct the site location which has been located by 2 of their surveyors 3' too close to the set back. The paper work submitted by them to planning is 3' off according to Peter Brewsters survey. How can you okay a site like that with paperwork in error and so many errors in the environmental assessment.



AT&T presented a woefully inaccurate environmental assessment at this site. They show no mines or historical mining activity nearby. Sierra Rock is clearly visible to the south, the property adjacent to this property. Many acres of gravel and sand removed and 2 tunnels going north toward this site. The frog pond is 60' north of this site, and was Joesph Snows hydraulic water containment pond in 1854. The pond still stores water, also an air shaft to the north of the site 30' deep. Also 2 hydrolic cuts with possible tunnels N.W of the sire in line with gravel pit. AT&T has had time to do ground penetrating radar and has failed to properly asses this site. The tower needs to be relocated.

CUP-A18-0005 Site 2 Newtown * Printed Name: Rachel Stoll Signature: //// Phone: 775 233 9677 Address: 147× Vista Del Ramcho PKung #138 10001ks 100 89436 E-Mail: racht story Rup live. com

AT&T presented a woefully inaccurate environmental assessment at this site. They show no mines or historical mining activity nearby. Sierra Rock is clearly visible to the south, the property adjacent to this property. Many acres of gravel and sand removed and 2 tunnels going north toward this site. The frog pond is 60' north of this site, and was Joesph Snows hydraulic water containment pond in 1854. The pond still stores water, also an air shaft to the north of the site 30' deep. Also 2 hydrolic cuts with possible tunnels N.W of the sire in line with gravel pit. AT&T has had time to do ground penetrating radar and has failed to properly asses this site. The tower needs to be relocated.

CUP-A18-0005 Site 2 Newtown	Ħ
Printed Name: honey Hens	
Signature: Courfoures	
Phone: 775-223-4360	
Address: 1173 SIMCroft Blue Pockule, MD 20850	
E-Mail: Khoemer auchou com	

AT&T presented a woefully inaccurate environmental assessment at this site. They show no mines or historical mining activity nearby. Sierra Rock is clearly visible to the south, the property adjacent to this property. Many acres of gravel and sand removed and 2 tunnels going north toward this site. The frog pond is 60' north of this site, and was Joesph Snows hydraulic water containment pond in 1854. The pond still stores water, also an air shaft to the north of the site 30' deep. Also 2 hydrolic cuts with possible tunnels N.W of the sire in line with gravel pit. AT&T has had time to do ground penetrating radar and has failed to properly asses this site. The tower needs to be relocated.

Printed Name: Signature: Phone: 39 Address: 2 E-Mail:

CUP-A18-0005 AT&T has had 6 months to correct the site location which has been located by 2 of their surveyors 3' too close to the set back. The paper work submitted by them to planning is 3' off according to Peter Brewsters survey. How can you okay a site like that with paperwork in error and so many errors in the environmental assessment.

Printed Name: Scot - Sowa Signature: Shatt Occupation: Bartender 530-621-3154 Phone: Address: 2686 2681 Glenview Drive E-Mail: <u>s-sowa@hotmail.com Placerville</u>, CA 95667

Printed N	ame:(nssell	Eide		
Signature	: <u> </u>	16	dy_	•	·
Occupatio	n: ///	an u facte	inly		
Phone:	530 9	19 95	81		
Address:	3216 K	Beam Ct	- Coorg	about	
E-Mail:	Mosserele				

Printed Name: Molly Cahill	
Signature: Molly Canin	
Occupation: Server / Wartender	
Phone: <u>530-957-6994</u>	
Address: mollycanili303 & gnail.com	
E-Mail: 12961 coloma St Unit B Placeruille CA	95667

Printed Name: Frider Vearson Signature: Bir Secret Occupation: HUAC Phone: <u>530-39(-8124</u> Address: 300 Reasont Valley Rd Diaword Springs E-Mail÷

Printed Name: Snerre mos Signature: Occupation: Fence Contractor Phone: 916-728-432 Address: 7512 Water Wals (E-Mail: Scene Thille Amarli Com

Printed Name: <u>John Homen</u> Signature: <u>John P. J. Homen</u> Phone: <u>330 - 64</u> 2 - 1754 Address: <u>2,80 V. 74 Grande CT</u> E-Mail: JR CR. Thomas of Stocked weth


This site needs to be moved because of many fatal faults in this location. This is an extreme danger fire area where some can not get fire insurance. This is an updraft area on Snow Ridge with 100mph winds at times a fure on or near this tower will endanger all of Rancho Del Sol. I have started the process to have a possible satellite fire station to house a fire truck that I have purchased.

an R Bren Printed Name: Signature: Occupation: naria Phone: 530- 957-0927 Address: 5390 Oaklanf Chat E-Mail: bakertan @ gmail.

We prefer the safety and security of having a real copper pair of wires and the speed and flexibility of fiber, over the placement of a cell tower at an inappropriate location on Snow Ridge in a high fire danger area.

• • •

Printed Name: Signature: WED Sheriff Corses Occupation: dis-Phone: 570. 1.51. 3248 Address: 3861 Intoszi. Ln S hinge E-Mail: the pailer @ att. ne



Printed Name: 🔪 orrip Signature: Occupation: Executive Assistant Phone: 8305 530-957 Address: 2971 Bedford ave apt 1 25667 E-Mail: Scherrie Wa) yahos. com

Printed Name: <u>RICK GAYLORD</u>	
Signature: <u>R. Saybod</u>	
Occupation: Technician, Teleconm	
Phone:	
Address:	
E-Mail: <u>sales@telefix.net</u>	

Printed Name: <u>Charse Warenes</u> Signature: <u>Grander Markenes</u> Phone: <u>976 766 1999</u> Address: <u>Chemical & Mottwin Hallon 19</u> E-Mail: <u>Cécil Cartantes Cell (2007</u>

This site meeds to be moved because of many fatal faults in this location. This is an extreme danger fire area where some can not get fire insurance. This is an updraft area on Snow Ridge with 100mph winds at times a fire on or near this tower will endanger all of Rancho Del Sol. I have started the process to have a possible satellite fire station to house a fire truck that I have purchased.

Printed Name: Robert V Rowland Signature: Kohet U Rowland Occupation: Rotie Phone: 330-676-1887 Address: 3931 crosswood Dr. Ghingle Spug. CH. E-Mail: None

Printed Name: Janna Paces Signature: Clamme Panne Phone: 916-710-62 Address: 222122 Claupst April 210 E-Maill: + among percent 0310300 grad <u>. C. C. MA</u>

This site needs to be moved because of many fatal faults in this location. This is an extreme danger fire area where some can not get fire insurance. This is an updraft area on Snow Ridge with 100mph winds at times a fire on or near this tower will endanger all of Rancho Del Sol. I have started the process to have a possible satellite fire station to house a fire truck that I have purchased.

Printed Name: Adriana Minio Signature; Occupation: SPIF employed love valil station Phone: 530-206-6080 Address: 3985 Stope Dr Placerillo E-Mail: greengardingir 11432 gmail

Printed Name: Ticia Han Signature: Occupation: Retirert Phone: <u>530-621-2213</u> Address: 6276 dickinson Rd Prille 01956 E-Mail: ticiaagna yehro.com