JBT MARINE

73 A WILBUR AVE. YUBA CITY, CA. 95991 SHOP 530-742-5752

| | INVOICE # | DATE | |
|---|---------------------------|-------------|--|
| | 202220 | 10/1/2021 | |
| | MECHANIC | WORK TYPE | |
| | ROBERT | FABRICATION | |
| | STATUS | STATUS DATE | |
| | F - Picked Up Not Paid | 5/5/2022 | |
| • | SEE SUPPLEMENT INV 202220 | | |

AUTHORIZATION:

seliasom@edso.ora

JON DENSMORE 530.306.9437 530.957.0418 MICHAEL SELIGHSOHN

EL DORADO COUNTY SHERIFF

BILL TO

| <u>3011930111@0030.0</u> | ng | | SEL SOLT ELMENT INV 202220 | | | |
|--------------------------|--------------|------------------|----------------------------|--|--|--|
| | | BOAT INFORMATION | | | | |
| Туре | Color | Hrs | Main Engine | | | |
| ROGUE JET | | 140 | | | | |
| CF # | Hull # | | Kicker Engine | | | |
| | RQJT1877E121 | | | | | |

| WK OF | SUMMARY DESCRIPTION OF WORK BY WEEK | QTY | UNIT PRICE | A | MOUNT | SHOP HRS |
|---|---|-----------------------|-----------------|--------------|---------------------------|----------|
| | ***FOR DETAIL BY DATE SEE PAGE 3 & 4*** | | | | | |
| 2021 TOTAI | DISSAMBLE & PREP 2021 - TOTAL | | | | | 18.50 |
| | HULL REPAIR STARBOARD SIDE WEEK 1 - TOTAL | | | | | 23.00 |
| - | HULL REPAIR STARBOARD SIDE WEEK 2 - TOTAL | | | | | 29.50 |
| | HULL REPAIR STARBOARD SIDE WEEK 3 - TOTAL | | | | | 15.00 |
| _ | HULL REPAIR PORT SIDE WEEK 4 - TOTAL | | | | | 32.50 |
| W/E_2/19 | HULL REPAIR PORT SIDE WEEK 5 - TOTAL | | | | | 30.00 |
| W/E_2/26 | HULL REPAIR PORT SIDE WEEK 6 - TOTAL | | | | | 32.50 |
| W/E_3/5 | HULL REPAIR PORT SIDE WEEK 7 - TOTAL | | | | | 21.99 |
| W/E_3/12 | HULL REPAIR INSIDE & SWIMDECK WEEK 8 - TOTAL | | | | | 31.50 |
| W/E_3/19 | HULL REPAIR KEEL & INSPECTION WEEK 9 - TOTAL | | | | | 14.75 |
| W/E_3/26 | HULL REPAIR GRIND, INSPECT & CHIMES WEEK 10 - TOTAL | | | | | 15.50 |
| W/E_4/2 | HULL REPAIR CHIME & GRINDING WEEK 11 - TOTAL | | | | | 23.75 |
| W/E_4/9 | HULL REPAIR REASSEMBLY & GRINDING WEEK 12 - TOTAL | | | | | 18.26 |
| W/E_4/23 | HULL REPAIR REASSEMBLY WEEK 13 - TOTAL | | | | | 20.83 |
| W/E_4/30 | HULL REPAIR BUFF, POLISH & CLEAN WEEK 14 - TOTAL | | | | | 31.80 |
| | | | | | | |
| | MICHAEL ANDERSON 530.621.6520 - MICHAEL.ANDERSON@EDCGOV.US | | | | - | |
| | | | | | - | |
| | | | | | - | |
| | ** SEE SUPPLEMENT WO 202294 FOR SIDE BUNKS AND TRANSOM TIE DOWNS | | | | - | |
| | | | | | - | |
| | SUPPLIES | | | | 200.00 | |
| | | 0741 | 40.05 | | | 250.00 |
| | I TAXABLE SERVICES NON TAX T | OTAL → | 13.95 | SHO | P HRS TOTAL \rightarrow | 359.38 |
| | DOUS WASTE FUEL @ \$4.00 per GAL | | | | - | |
| HAZAR | DOUS WASTE OIL @ \$2.00 per GAL | | | | - | |
| HAZAR | DOUS WASTE COOLANT @ \$1.60 per GAL | | | | - | |
| SHIPPI | NG: | | 13.95 | | 13.95 | |
| | Thank you for your business! | TAXABL | E SUBTOTAL | \$ | 3,778.63 | |
| JBT MARINE employees may operate above vessel and trailer for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above | | TAX @ | 7.25% | \$ | 273.95 | |
| | | E IBOIL & VIED LEITIN | | \$ 44,922.50 | | |
| | nd trailer to secure that JBT MARINE will not be held responsible for loss or damage ressel or trailer or articles left in the vessel or trailer in case of fire, theft, amount of | Minus Dej | oosit & Credits | \$ | - | |
| | repairs thereta posident or any other says havend any control | | | | | |

TOTAL

repairs thereto, accident or any other cause beyond our control.

CUSTOMER SIGNATURE

I hereby authorize the above repair work to be completed along with any applicable parts and/or materials.

ANY BOAT LEFT OVER 15 DAYS AFTER COMPLETION IS SUBJECT TO A \$25.00 PER DAY STORAGE FEE

JBT MARINE HONORS A 30 DAY WARRANTY ON PARTS AND LABOR

\$ 48,989.03

JBT MARINE

| | ΟΤΥ | | ^ | MOUNT | |
|--|-------------------|----------------------|----------|--------------------|----------|
| ITEMIZED PARTS LIST | QTY | | | MOUNT 257.69 | SHOP HRS |
| BENNETT BOLT ELECTRIC ACTUATOR BEA2000 | 1 | \$ 257.69 \$ 2.20 | | 257.69 | |
| CARPET FOR INSIDE OF HULL sq ft | 96 | | | | |
| ALUMINUM SHEET 1/4" 5' X 8' | 1 | \$ 1,090.00 | \$ \$ | 1,090.00 963.00 | |
| ALUMINUM SHEET 1/8" sq in | 1.5 | \$ 642.00 | | 963.00 47.36 | |
| ALUMINUM ANGLE 1-1/2" X 1-1/2" X 1/8" lin ft | 16 | \$ 2.96 | \$ | | |
| ALUMINUM ANGLE 1" X 1" X 1/8" | 16 | \$ 3.84 | \$ | 61.44 | |
| ALUMINUM SHEET 3/16" X 5' X 8' | 1 | \$ 612.00 | \$ | 612.00 | |
| ALUMINUM TUBING 3-1/2 X 3-1/2 X 1/4 WALL IN | 211 | \$ 2.54 | \$ | 535.94 | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | _ | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ \$ | | |
| | | | \$ \$ | - | |
| | | | | | |
| | | | \$ ¢ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | Ş | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | \$ | - | |
| | | | | ditional Shop | |
| Additional Taxable Items T | $TAL \rightarrow$ | \$ 3,778.63 | 7.0 | Hrs → | - |
| | | | | 1113-7 | |

Vince DiLeo Marine Surveyor email: survey@admiraltyservices.com cell: 775.560.8088.

4

| DATE | DESCRIPTION OF WORK - IN DETAIL BY DATE | SHOP HRS |
|---------------|---|----------|
| 10/4 PI | ULLED SEATS & FLOORING | 3.00 |
| 11/23 PI | ULLED FUEL TANK | 2.50 |
| 11/24 ⋈ | IODIFY MOTOR STAND / DISCONNECT STB MOTOR | 5.00 |
| 11/29 RI | EMOVED - STB MOTOR / TRIM TAB / STB BATTERY & FLOORDISCONNECTED & REMOVED PORT MOTOR | 4.00 |
| 11/30 F/ | ABRICATE/MODIFY BOAT CART FOR LIFTING/TILTING/TESTING | 4.00 |
| | ISSAMBLE & PREP 2021 - TOTAL | 18.50 |
| | UT OUT STB SIDE | 7.00 |
| | EMOVE WIRES & BILGE HOSE FOR ACCESS / CUT & REMOVE HULL SECTION | 5.00 |
| | EPAIR HULL | 3.00 |
| | | |
| | EPAIR HULL | 3.00 |
| | UT & BEND MATERIAL / PREP SECTION AREA FOR REPAIR | 5.00 |
| | ULL REPAIR STARBOARD SIDE WEEK 1 - TOTAL | 23.00 |
| | EPAIR HULL - STARBOARD SIDE | 6.00 |
| 1/25 RI | EPAIR HULL - STARBOARD SIDE | 6.00 |
| | EPAIR HULL - STARBOARD SIDE | 6.00 |
| 1/27 PI | ULL BATTERY & FLOOR PORT SIDE / FINISH HARD TO GET WELDS / TACK IN PLACE FAB PIECE | 7.50 |
| 1/28 C | ONTINUE WELDING STARBOARD SIDE | 4.00 |
| W/E_1/29 H | ULL REPAIR STARBOARD SIDE WEEK 2 - TOTAL | 29.50 |
| 1/31 FI | NISH WELDS STARBOARD SIDE / GRIND OUTSIDE | 6.00 |
| 2/1 FI | NISH GRIND / START PORT SIDE REPAIR (START CUT) | 7.00 |
| 2/2 CI | UT OUT PORT SIDE | 1.00 |
| | TAGE BOAT | 1.00 |
| , | ULL REPAIR STARBOARD SIDE WEEK 3 - TOTAL | 15.00 |
| _ | EPAIR HULL - PORT SIDE | 4.50 |
| 2/7 | EPAIR HULL - PORT SIDE | 7.00 |
| | REP PORT AFT SECTION FOR INSTALL OF NEW METAL | 7.00 |
| | | |
| | UT & INSTALL HULL PIECE PORT SIDE | 7.00 |
| | ISTALL & WELD STRINGER PIECES TO HULL - PORT SIDE | 7.00 |
| _ | ULL REPAIR PORT SIDE WEEK 4 - TOTAL | 32.50 |
| | ONTINUE WELDING AFT PORT HULL BOTTOM SECTION / FAB PORT SIDE PIECE | 7.00 |
| | ACK & WELD PORT AFT | 7.00 |
| | /ELD PORT SIDE | 2.50 |
| 2/17 FI | NISH WELDING PORT AFT REAR & START PORT BOW SECTION | 7.00 |
| 2/18 CI | UT OUT BOW TO MID PORT SECTION | 6.50 |
| W/E_2/19 H | ULL REPAIR PORT SIDE WEEK 5 - TOTAL | 30.00 |
| 2/21 RI | EPAIR STARBOARD MID SECTION HULL | 6.50 |
| 2/22 T/ | ACK IN PLACE MID HULL / START WELD | 5.50 |
| 2/23 W | /ELD STRINGER TO HULL / WORK ON PORT SIDE HULL | 7.00 |
| 2/24 C | ONTINUE HULL WELDS / START SIDE FABRICATION | 6.50 |
| 2/25 F/ | ABRICATE & WELD PORT SIDE BOW | 7.00 |
| | ULL REPAIR PORT SIDE WEEK 6 - TOTAL | 32.50 |
| | ONTINUE WELDING PORT SIDE / START OFF SHORE BRACKET | 6.83 |
| | ONTINUE WELDING / INSPECT & TOUCH UP CURRENT WELDS | 6.33 |
| 0/- | LEAN UP OFF SHORE BRACKET / FABRICATE & BEND BOTTOM FOR OFFSHORE BRACKET | 4.83 |
| -/- | REP FOR OFFSHORE BRACKET WELD / CUT HULL PIECE TO SIZE | 4.00 |
| | ULL REPAIR PORT SIDE WEEK 7 - TOTAL | |
| | | 21.99 |
| 0,1 | ACK IN SWIM DECK HULL & START WELDING | 6.00 |
| - / - | INISHING WELDING SWIM DECK INSIDE&OUTSIDE / START GRINDING BOTTOM | 6.00 |
| - / - | ONTINUE GRINDING BOTTOM / LEAK TEST | 6.50 |
| | RIND PORT SIDE / TACK & WELD TRIM TAB BRACKETS | 6.00 |
| | /ELD STARBOARD SIDE STRINGERS / WELD FRONT KEEL SUPPORT / START KEEL INTSTALL | 7.00 |
| | ULL REPAIR INSIDE & SWIMDECK WEEK 8 - TOTAL | 31.50 |
| 3/14 G | RIND & PREP AREAS FOR INNER KEEL SUPPORT / WELDED INNER KEEL SUPPORT / TACK IN KEEL / WELD KEEL | 10.50 |
| 3/15 IN | ISPECT & TOUCH UP CURRENT WELDS | 2.00 |
| 3/16 FI | X PORT SIDE MISMATCHES | 1.50 |
| | X PORT SIDE MISMATCHES | 0.75 |
| | ULL REPAIR KEEL & INSPECTION WEEK 9 - TOTAL | 14.75 |
| | RIND & REMOVE CHIME | 0.75 |
| | /ORK ON, INSPECT & GRIND PORT SIDE WORK | 2.50 |
| 5,25 | ORT SIDE STRESS INSPECTION / START CHIMES | 7.25 |
| 2/2/ 0 | ON SIDE STRESS INSI ECHONY STANT CHINIES | 1.73 |
| | ABRICATE, INSTALL & WELD STARBOARD CHIMES / FABRICATE PORT SIDE CHIMES | 5.00 |

4

| DATE | DESCRIPTION OF WORK - IN DETAIL BY DATE | SHOP HRS |
|----------|---|----------|
| 3/28 | TACK IN & WELD PORT SIDE AFT | 6.25 |
| 3/29 | FINISH WELDS PORT SIDE INSIDE / WELD IN ANGLE SIDE SUPPORT / FILL SCREW HOLES / CUT PORT SIDE OUTER CHIME / CLEAN GRIND MARKS | 5.25 |
| 3/30 | TACK IN CHIME / CLEAN HULL / GRIND PORT SIDE | 6.00 |
| 3/31 | GRIND PORT SIDE / TACK INNER PORT CHIME | |
| 4/1 | FINICH TACK OF CHIME & WELD / GRIND PORT SIDE | 6.25 |
| W/E_4/2 | HULL REPAIR CHIME & GRINDING WEEK 11 - TOTAL | 23.75 |
| 4/4 | REINSTALL & HOOK UP MOTORS | 6.50 |
| 4/5 | FINISH MOTOR HOOK UP / INSTALL TRIM TABS / LEAK TEST AT RIVER / START PORT INNER FLOOR SUPPORT INSTALLATION | 6.50 |
| 4/6 | FABRICATE & INSTALL CORNER PIECES / GLUE IN BILGE PUMP | 4.33 |
| 4/8 | GRIND PORT SIDE | 0.93 |
| W/E_4/9 | HULL REPAIR REASSEMBLY & GRINDING WEEK 12 - TOTAL | 18.26 |
| 4/14 | WELD PIN HOLES ON SIDES | 5.50 |
| 4/18 | HOOK UP BILGE PUMPS / COSMETIC REPAIR OF KEEL AND BOAT BOTTOM | 6.00 |
| 4/19 | HOOK UP POWER STEERING & WASH DOWN/ PLUG SCREW HOLES / INSTALL FUEL TANKS / FINISH BOTTOM | 6.00 |
| 4/20 | WLED IN FLOOR SUPPORTS / PLUG HOLES / HOOK FUEL TANK & FOAM TANK SIDES / REINSTALLED BATTERIES | 3.33 |
| W/E_4/23 | HULL REPAIR REASSEMBLY WEEK 13 - TOTAL | 20.83 |
| 4/25 | INSTALLED CARPET / WIRED LIGHTS / SANDED & BUFFED OUTER HULL | 7.00 |
| 4/26 | SANDED OUTER HULL | 12.00 |
| 4/27 | BUFFED & POLISHED OUTER HULL | 10.00 |
| 4/28 | BUFFED OUTER HULL / SWEPT, VACUUMED & CLEANED BOAT | 2.80 |
| W/E_4/30 | HULL REPAIR BUFF, POLISH & CLEAN WEEK 14 - TOTAL | 31.80 |
| | TOTAL SHOP HOURS DETAILED LABOR\$ 44,922.50 HRS | 359.38 |