General Fund

| 1.0 Million | | | | | | |
|----------------------|--|--------|--------|--|--|--|
| Type of Work | Roadway | Cost | PCI | Description | | |
| Rehabilitation | Marshall Road (End of Tribe to Garden Valley Rd) | \$300K | 36 | Rehab to perform is grind/pave, brushing, ditching, drainage improvements. Materials and hauling services only | | |
| Rubberized Cape Seal | El Dorado Hills Business Park 1) Cypress Point Ct 2) Glenhaven Ct 3) Golden Foothill Pkwy 4) Hawk's Flight Ct 5) Hillsdale Cir 6) Investment Blvd 7) Robert J Mathews Pkwy 8) Suncast Ln 9) Sunglow Ct 10) Windfield Wy 11) Windplay Dr | \$700K | Avg 63 | Rubberized Chip and Slurry Seal. Performed by outside contractor | | |
| | 2.0 Mi | | | | | |
| Type of Work | Roadway | Cost | PCI | Description | | |
| Rubberized Cape Seal | Marshall Road (End of Tribe to Garden Valley Rd) | \$300K | 36 | Rubberized Chip and Slurry Seal. Performed by outside contractor | | |
| Rehabilitation | El Dorado Hills Blvd (Olsen to Francisco) | \$300K | 54 | Rehab includes grind/pave (materials and hauling services only) | | |
| | Mtn Meadow Drive | \$65K | 41 | Rehab includes grind/pave (materials only) | | |
| | Angora Creek Drive | \$65K | 33 | Rehab includes grind/pave (materials only) | | |
| | Apache Ave (lower section) | \$125K | 14 | Rehab includes grind/pave (materials only) | | |
| Slurry Seal | Camino Hills Subdivision 1) Camino Hills Dr 2) Halcon Rd 3) Manzana Ct 4) Monte Vista Dr 5) Vista Del Mundo 6) Vista Tierra Dr | \$55K | Avg 94 | Slurry Seal performed outside contractor. Preserve the roadway for another 7-10 years. | | |

| 3.0 Million | | | | | | | |
|----------------------|--|--------|--------|---|--|--|--|
| Type of Work | Roadway | Cost | PCI | Description | | | |
| | Mt. Aukum Rd (Bucks Bar Rd to Fairplay Road) | \$150K | 46 | | | | |
| Rehabilitation | Grizzly Park Subdivision (Section 1) 1) Capps Crossing Rd 2) Cypress Point Dr 3) Deertract Ct 4) Deerwood Ct 5) Edgewood Cir 6) Forest Glen Dr 7) Grizzly Creek Dr 8) Meadow Glen Dr 9) Merrywood Ct 10) No Name 11) Parkside Ct 12) Parkside Dr 13) Pinehaven Dr 14) Quietwood Dr 15) South View Dr 16) Storybook Ct 18) Tyler Dr 19) Winding Way 20) Winding Way Ct | \$150K | Avg 44 | Rehab to perform is grind/pave, brushing, ditching, drainage improvements. Money provided is for materials and hauling services | | | |
| Rubberized Cape Seal | Grizzly Park Subdivision (Section 1) | \$700K | Avg 44 | Rubberized Chip and Slurry Seal. Performed by outside contractor | | | |

Tribe

| | 1.25 Millio | on | | |
|----------------------|---|--------------------------------------|--------------------------|--|
| Type of Work | Roadway | Cost | PCI | Description |
| Rehabilitation | Marshall Road (Tribe Section) | \$745K | 32 | Rehab to perform is grind/pave, brushing, ditching, drainage improvements. (Labor, materials and hauling services) |
| Brushing | Cold Springs Road | \$425K | N/A | Brushing for fuel reduction, site distance improvements. |
| Roadway Striping | Tribal Area | \$80K | N/A | Materials for Striping |
| | 2.50 Millio | on | | |
| Rehabilitation | Diamond Springs Business Park 1) Bright Ct 2) Capitol Ave 3) Clear Ct 4) Commerce Wy 5) Enterprise Ct 6) Enterprise Dr 7) Industrial Dr 8) Merchandise Wy | \$275K | Avg 38 | Rehab to perform is grind/pave, brushing, ditching, drainage improvements. Money provided is for materials and hauling services. |
| Rubberized Cape Seal | Meder Rd Marshall Road (Tribe Section) Diamond Springs Business Park Meder Rd | \$205K \$200K \$120K \$300K | 68 32 Avg 38 68 | Rubberized Chip and Slurry Seal. Performed b outside contractor |
| | Pleasant Valley Road (Oriental to Mother Lode Dr) | \$150K | 61 | |