

RDRS Quarterly Report Summary 2023 Quarter 1

Summary Information for Reporting Entity Filing Report

Organization/Site:

Union Mine Disposal Facility

Reporting Entity Name:

Union Mine Wastewater Treatment Facility

RDRS #: RD10577

Reporting Entity Activity: Recycler/Composter

Report Summary Generated On:

May 1, 2023

Physical Address:

5700 Union Mine Road, El Dorado, California 95623

Mailing Address:

2850 Fairlane Court, Building C, Placerville, California 95667

Quarterly Report Submittal Information

Organization/Site:

Union Mine Disposal Facility

Report Year/Quarter:

2023 Q1

Submittal Status:

Submitted

Reporting Exemption:

No

Reporting Exemption Type:

N/A

Submitted On:

May 1, 2023

Last Revised On:

N/A

Revised Report:

No

Revision Number:

Original Submission

Submitted By:

Robert Brillisour

Phone:

(530) 295-0429

E-mail:

rob.brillisour@edcgov.us

Primary Contact:
Robert Brillisour
Signature Authority:

Robert Brillisour

Quarterly Report Revision History

Revision Number	Started On	Submitted On
Original Submission	05/01/2023	05/01/2023



Outflows

Outflow Streams Sent

Non-Green Material for Potential Beneficial Reuse

Outflow Summary

Outflow Stream	Total Tons Sent
Non-Green Material for Potential Beneficial Reuse	197.62

Outflow Methodology

Questions on how outflow tons are determined and jurisdiction of origin is tracked.

Method(s) Used To Determine Tons Sent

- Track outflow amounts based on my own measurements of the following:
 - Track material weight using my own certified scales
- Rely on the receiving facility or business to provide outflow amounts based on the facilities measurement of tons using the following methods:
 - Track material weight using facility certified scales

Outflow Detail by Material Stream

Non-Green Material for Potential Beneficial Reuse

Organization/Site	Reporting Entity Name (RDRS #)	Tons Sent	Material Type(s)
Potrero Hills Landfill, Inc.	Potrero Hills Landifll, Inc (RD10775)	197.62	Biosolids
Total		197.62	



Organics Measurement

Is your reporting entity a composting or an in-vessel digestion operation, or do you have at least one dependent composting and/or in-vessel digestion operation on site that is active and required to report? No



Review Flags

Review and Submit Status (Flags generated and reviewed)

Severity	Status	Source	Туре	Description
Informational	N/A	Outflows	Tons of total material sent out for disposal different than prior years same quarter by significant amount (exceeds threshold).	The total tons of MSW sent to disposal facilities and/or other transfer/processors in 2023 Q1 by your facility was significantly different (50% or more) than the amount sent out in the prior year same quarter. This flag appears to notify you of significant change in outflow and help you determine if there are any data entry errors or issues in reporting accuracy in your report.
Informational	N/A	Outflows	Tons of total material sent out for potential beneficial reuse (Green and non-green) different than prior years same quarter by significant amount (exceeds threshold).	(non green material) The total tons of non green material potential beneficial reuse sent to disposal facilities and/or other transfer/processors in 2023 Q1 by your facility was significantly different (50% or more) than the amount sent out in the prior year same quarter. This flag appears to notify you of significant change in outflow and help you determine if there are any data entry errors or issues in reporting accuracy in your report.



Documents

Documents Added to the Report

Document Type	Title	Description	Document Date	File Name	
There are no documents.					